



# DHRUTI DESIGN SERVICES

208, Sai Tirumala Towers, Hyderguda, Hyderabad - 29.  
Ph: (040) 30284333, 334, 335, 336. Fax : 040-30284337.  
e-mail: infodhruti@gmail.com

*Architects Industrial Designers  
Engineers Project Managers*

## ARCHITECT'S CERTIFICATE

Based on Site Inspection, with respect to each of the Buildings /Blocks/Towers of SREE RAMA ENGINEERING COLLEGE, I certify that as on the date of this certificate, the Percentage of Work done for each of the Buildings /Blocks/Towers of SREE RAMA ENGINEERING COLLEGE as registered vide number BA No. 447/G2/07 Dated 17.02.2007 under. The percentage of the work executed with respect to each of the activity of the entire phase is detailed in the Table below.

### Internal & External Development Works in Respect of the Entire Registered Phase

S No	Common Areas and Facilities, Amenities	Proposed (Yes/No)	Details	Percentage of Work done
1	Internal Roads & Footpaths	Yes	Constructed as per Norms	<b>100 % of work is completed</b>
2	Water Supply	Yes	Constructed as per Norms	<b>100 % of work is completed</b>
3	Sewerage (chamber, lines, Septic Tank)	Yes	Constructed as per Norms	<b>100 % of work is completed</b>
4	Strom Water Drains	Yes	Constructed as per Norms	<b>100 % of work is completed</b>
5	Landscaping & Tree Planting	Yes	Constructed as per Norms	<b>100 % of work is completed</b>
6	Street Lighting	Yes	Constructed as per Norms	<b>100 % of work is completed</b>
7	Treatment and disposal of sewage and sullage water	Yes	Constructed as per Norms	<b>100 % of work is completed</b>



# DHRUTI DESIGN SERVICES


208, Sai Tirumala Towers, Hyderguda, Hyderabad - 29.  
Ph: (040) 30284333, 334, 335, 336. Fax : 040-30284337.  
e-mail: infodhruti@gmail.com

Architects Industrial Designers  
Engineers Project Managers

8	Solid Waste management & Disposal	Yes	Constructed as per Norms	<b>100 % of work is completed</b>
9	Water conservation, Rain water harvesting	Yes	Constructed as per Norms	<b>100 % of work is completed</b>
10	Energy management	Yes	Constructed as per Norms	<b>100 % of work is completed</b>
11	Fire protection and fire safety requirements	Yes	Constructed as per Norms	<b>100 % of work is completed</b>
12	Electrical meter room,	Yes	Constructed as per Norms	<b>100 % of work is completed</b>
13	Other (Option to Add more)	Nil	Nil	Nil

Signature of the Architect  
Name of the Architect: Ar. S. SREEDHAR REDDY  
Registration  
No : CA/2001/28517  
Date : 29/01/2018

Seal

  
**Ar. S. SREEDHAR REDDY**  
**REGISTERED ARCHITECT**  
**Regd. No: CA/2001/28517**

Place: Tirupati.